





	100
	F 41
	AxB 100x85
	AAxBB 80x60
	EE 9
	E 42
	LC 220



Code for high and low temperatures bracket

GZ10040HT

Code for high and low temperatures bracket with dust protection ring

GZ10040HTR
