


+300°C -40°C







Code for plain bore wheel



Code for wheel with coated bush





Code for wheel with double BT self-lube bush



Code for wheel with double HT ball bearing



Code wheel with double sintered bronze bush

